

High Temperature Calvet Calorimeter (Setaram, France)



Used to measure

1. Enthalpy of formation
2. Enthalpy of mixing
3. Heat capacity

Temperature range: 298-1000 K

Heat capacity and enthalpy of formation of large number of compounds of fission products of AHWR system have been determined.